

Oil Field Environmental Incident Summary

Incident: 20150803170644 **Date/Time of Notice:** 08/03/2015 17:06

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: BOSTON 1-25H

Field Name: BROOKLYN

Well File #: 22143

Date Incident: 8/1/2015 **Time Incident:** 12:00

Facility ID Number:

County: WILLIAMS

Twp: 155

Rng: 98

Sec: 25

Qtr:

Location Description: Ditch on the South side of 56th St NW.

Submitted By: Timothy Ilse

Received By:

Contact Person: Brett Olson
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Other - Described Above

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: No

Reported to NRC: No

Spilled Units

Recovered Units

Followup Units

Oil

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

10 ft. by 40 ft. area

Potential Environmental Impacts:

Vegetation

Action Taken or Planned:

Extinguished the fire

Wastes Disposal Location: None

Agencies Involved: Called John Rumppe @ 12:30 on 8/3/2015

Updates

Date: 8/4/2015 **Status:** Inspection

Author: Kangas, Kathleen

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Fire impact extends from flare pit to ditch, approximately 20 feet wide and 70 feet long along roadway. No cleanup has occurred yet. Follow-up with company rep on cleanup is required.

Date: 8/4/2015 **Status:** Reviewed - Follow-up Required

Author: Crowds, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Fire, impacted areas off location. Follow-up is required.

Date: 9/11/2015 **Status:** Inspection

Author: Kangas, Kathleen

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On-site 09/09/2015 at 4:15 pm. Weather is 66 degrees F, partly cloudy, wind 9mph North. Fire debris appears cleaned up. New grass growth seen.

Date: 3/10/2016 **Status:** Correspondence

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Bill Suess sent a No Further Action letter dated March 10, 2016.